

CADDX 9000

- 1. TO BYPASS:** PRESS * ZONE NUMBER (i.e. 01,02) *
- 2. TO ARM:** ENTER 4 DIGIT CODE
- 3. INSTANT:** PRESS * AFTER ARMING THIS WILL REMOVE THE
30 SECOND DELAY TIME
- PANIC: *#** PRESSED AT THE SAME TIME
- FIRE: 1, 3** PRESSED AT THE SAME TIME
- DURESS: 4 DIGIT CODE** SENDS SILENT SIGNAL TO MONITORING STATION
- PROGRAMMING:**
- MASTER CODE:** C, 01, PRESENT MASTER CODE, NEW MASTER CODE
- AUXILLIARY CODES:** C, 02, (03,04....30), MASTER CODE, NEW CODE
- DURESS CODE:** C, 15, MASTER CODE, 4 DIGIT DURESS CODE

*** CODE NUMBER 15 CANNOT BE USED IF PROGRAMMING FOR A DURESS CODE***